

Control # 019120130328 019020130328 018920130328 018820130328 018720130328

Date Taken	03/28/2013	03/01/2013	02/01/2013	01/01/2013	12/01/2012
Service Meter Reading	0	0	0	0	0
Fluid Run Time	0	0	0	0	0
Fluid Added Gal / Qts	0 / 0	0 / 0	0 / 0	0 / 0	0 / 0
Fluid Status	Sampled	Sampled	Sampled	Sampled	Sampled
Filter Changed	Unknown	Unknown	Unknown	Unknown	Unknown
Water	Trace	Negative	Negative	Negative	Negative
Visc 40C	44.8	43.8	43.0	43.2	42.5
TAN	0.68	0.60	0.60	0.56	0.50
Iron (FE)	8	4	3	3	3
Chrome (CR)	1	1	1	1	0
Lead (PB)	0	0	0	1	2
Copper (CU)	28	18	20	15	10
Tin (SN)	1	2	3	1	1
Aluminum (AL)	0	2	1	0	0
Nickel (NI)	0	0	0	0	2
Silver (AG)	0	0	0	0	0
Silicon (SI)	22	8	11	10	8
Potassium (K)	0	0	0	0	0
Sodium (NA)	11	9	6	2	2
Boron (B)	0	0	0	0	0
Magnesium (MG)	2	2	2	1	4
Calcium (CA)	63	60	51	55	52
Barium (BA)	0	0	0	0	0
Phosphorus (P)	365	319	350	336	316
Zinc (ZN)	418	426	403	419	451
Moly (MO)	0	0	2	0	0
Titanium (TI)	0	0	0	0	0
Vanadium (V)	1	0	0	0	0
Water Content	606ppm	84ppm	48ppm	63ppm	54ppm



Lab One Inc.

Oil Analysis since 1985

Mail to: PO Box 20210 - Phoenix, AZ 85036-0210

Ship to: 101 W Mohave St. - Phoenix AZ 85003

Phone

Local: 480-839-5221
Toll Free: 866-652-2663
Fax: 480-839-9987

Reportable

1 of 1

03/29/2013

Make / Model

Unit/Serial

BOW EXAMPLE/

Compartment

Bow Example Report

Fluid Type

WO / Reference

Current Interpretation

Copper Level Has Increased. Silicon Level Increased. Water Detected In Trace Amount. Check For Source Of Water Entry. Perform Appropriate Diagnostics. Resample To Check Wear Trend.

000000084

Lab One Web Test
Attn: Jason Kronlund
101 West Mohave Street
Phoenix, AZ 85003

Registered By

JASON KRONLUND

Interpreted By

JASON KRONLUND